Reactor System Technology D

Derivation of Limit Stress Curve Equation

Hwanho Lee
Kijang Research Reactor Design and Construction Project, KAERI

CONTENTS

01 Introduction

01 Introduction

Limit analysis

- For stress analysis, limit analysis is a special case of plastic analysis in which the material is assumed to be ideally plastic (nonstrain-hardening) [1].

- Using this assumption, the stress limit was developed by providing a margin on the actual limit load stress curve for combined tension and bending on a rectangular section [2].

- In this study, the limit stress curve equation is derived and the results are compared to reference.

02
Methods and Results

Limit stress curve



- Limit stress for combined tension and bending (rectangular section). (ASME, "Criteria," Courtesy of ASME)

- In limit analysis, the equilibrium and flow characteristics at the limit state are used to calculate the collapse load.

- In this figure, we can't know how the limit stress curve was drawn and what the exact coordinates were.

- From equilibrium equations, the limit stress curve equation can be derived.

02 Methods and Results

» Decomposition of stress components



- A plastic hinge is an idealized concept used in Limit Analysis. In a beam or a frame, a plastic hinge is formed at the point where the moment, shear, and axial force lie on the yield interaction surface [1].

- In the perfectly plastic state, the cross section of the neutral axis is divided into two equal areas.

Derivation of limit stress curve equation



$$(1-y)S_y \cdot a = (1+y)S_y \cdot (d-a) \quad (1)$$

$$\therefore a = \frac{d}{2}(1+y) \quad (2)$$

$$M_1 = (1-y)S_y \cdot ab\frac{a}{2} \quad (3)$$

$$M_2 = (1+y)S_y(d-a) \cdot b\frac{1}{2}(d-a) \quad (4)$$

Moment $M = M_1 + M_2$

$$= \frac{1}{2}S_y b\{(1-y)a^2 + (1+y)(d-a)^2\} \quad (5)$$

Substituting Eq. (2) in (5) gives

$$M = \frac{1}{4}Sybd^2(1-y^2) \quad (6)$$

Tensile stress $P_m = yS_y,\ y = \frac{P_m}{S_y}$ (7)

Bending stress $P_b = \frac{M}{(bd^2)/6}$ (8)

Substituting Eq. (8) in (6) gives

$$P_b = \frac{3}{2}S_y(1-y^2) \quad (9)$$

For the axes form of the limit stress curve, Eq. (7) and (9) gives

$$\frac{(P_m + P_b)}{S_y} = \frac{P_m}{S_y} + \frac{3}{2}\left\{1 - \left(\frac{P_m}{S_y}\right)^2\right\} \quad (10)$$

$$\therefore \frac{(P_m + P_b)}{S_y} = -\frac{3}{2}\left(\frac{P_m}{S_y} - \frac{1}{3}\right)^2 + \frac{5}{3} \quad (11)$$

Korea Atomic Energy Research Institute

02 Methods and Results

» Limit stress curve equation



$$\frac{(P_m + P_b)}{S_y} = -\frac{3}{2}\left(\frac{P_m}{S_y} - \frac{1}{3}\right)^2 + \frac{5}{3}$$

- From this equation, we can understand the limit stress curve and analogize the whole out of a part.

- This figure indicates that the theoretical limit stress varies from 1.5 Sy with no membrane stress present to 1.0 Sy with only membrane stress present. It should be noted that the theoretical limit stress peaks at approximately 1.67 (=5/3) with a combination of bending and membrane stress when the membrane stress is approximately (1/3)Sy [2].

03 Conclusions

03 Conclusions

- In this study, the limit stress curve equation is derived from moment equilibrium and the results are compared to reference.

- From the results, we can figure out the meaning and purpose of the limit stress.

- This theoretical limit could be expanded to Class 2 and 3 Components.

04

Acknowledgement & References

04 Acknowledgements & References

» Acknowledgements

- This work was supported by the National Research Foundation of Korea (NRF) grant funded by the Korea government (MSIT: Ministry of Science and ICT) (No. 2020M2C1A1061043).

» References

[1] ASME Boiler and Pressure Vessel Code, Section III, Subsection NB, Class 1 Components, American Society of Mechanical Engineers, 2004.

[2] K. R. Rao, Companion Guide to the ASME Boiler & Pressure Vessel Code, ASME Press, 2009.

THANK YOU